

XIAOMI 5	*	*	*	*	*	*	✓	✓	*	✓	✓	*	*	*	*	*	*	✓	*	✓	*	*	*	*	✓	*	✓	✓	*	*	*	*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Sony XPERIA Z5	✓	*	*	*	*	*	✓	✓	*	✓	✓	*	*	*	*	*	*	✓	✓	✓	✓	✓	*	*	*	✓	*	*	*	*	✓	✓	✓	✓ ²	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

¹ - Pairing may timeout without finding the Garmin device, requiring additional attempts to pair Garmin devices. Once initial pairing has been completed connections between the device and this phone are stable.
² - Garmin Connect Mobile may notify you that your phone or Garmin device need to be restarted when an unstable BLE connection occurs, or when the app cannot reconnect to a previously connected BLE device.
³ - Reconnection times between this phone and Garmin devices are longer than other Garmin device and phone combinations.
x - Device and phone combination did not pass our internal tests. The phone and device may work together, but will likely require regular Bluetooth troubleshooting.
* - Device and phone combination have not been tested.

Is your phone not listed? Garmin will attempt to keep this list up to date with the most popular Smartphones that feature Bluetooth Smart technology however it will be possible that a particular model may work but not be listed as compatible.

If your Smartphone is not listed above, it is possible for it to be compatible if it meets the following requirements:

- **Android 4.3 OS and above**
- **Bluetooth 4.0 capable**